







HOW TO MEASURE LENGTHS

Length of fasteners are all measured by usable/functional length, see examples below.

	<p>Countersunk Flat Head</p>			<p>Countersunk Oval Head</p>
	<p>Pan Head</p>			<p>Hex Head</p>
	<p>Truss Head</p>			<p>Shoulder Bolt</p>