

## INFORMATION NEEDED TO CALL OUT A PART

### Machine Screw Example

1/4-20 x 1-3/4 PH PAN HEAD MACHINE SCREW ZINC

1/4	20	1-3/4	PH	PAN	M/S	STL	ZINC
DIAMETER	THREAD PITCH	LENGTH	DRIVE	HEAD STYLE	SCREW TYPE	MATERIAL	COATING

### Nut Example

1/2-13 Finished Hex Nut GD 8 Zinc Yellow

1/2	13	HEX	FINISHED	NUT	GD 8	ZINC YELLOW
DIAMETER	THREAD PITCH	NUT SHAPE	NUT TYPE		MATERIAL	COATING TYPE

### Bolt Example

3/8-16 X 2-1/4 CARRIAGE BOLT GD 5 ZINC

3/8	16	2-1/4	CARRIAGE	BOLT	GD 5	STEEL	ZINC
DIAMETER	THREAD PITCH	LENGTH	BOLT TYPE		MATERIAL GD	MATERIAL	COATING TYPE

### Washer Example

5/16 X 1-1/4 FENDER WASHER BRASS NICKEL

5/16	1-1/4	FENDER	WASHER	BRASS	NICKEL	
BOLT SIZE	OD	WASHER TYPE		MATERIAL	COATING TYPE	OTHER INFORMATION







### Screw Example

#10-12x 3 PH PAN HEAD SHEET METAL SCREW TY A ZINC

#10	12	3	PHILLIPS	PAN	SMS TY A	STEEL	ZINC
DIAMETER	THREAD PITCH	LENGTH	DRIVE STYLE	HEAD STYLE	TYPE OF SCREW	MATERIAL	COATING TYPE

## HOW TO MEASURE LENGTHS

*Length of fasteners are all measured by usable/functional length, see examples below.*

	<p>Countersunk Flat Head</p>			<p>Countersunk Oval Head</p>
	<p>Pan Head</p>			<p>Hex Head</p>
	<p>Truss Head</p>			<p>Shoulder Bolt</p>